General Auto Handling

- 1. Drivers must maintain safe speed and distance on vessel and pier.
- 2. No passing or speeding at any time. NO EXCEPTIONS!
- 3. Drivers will not move auto's without the assistance of a spotter in tight areas.
- 4. No exposed jewelry, watches, rings, keys, etc.
- 5. Discharge route will be coned off.
- 6. Ensure all windows are up and keys placed in proper location.
- 7. Make sure emergency break is on and if it is a manual transmission that it be put in 1st gear.
- 8. Lashers must have knee pads or any pads underneath there pants or jumpsuits.
- 9. Lashers must be wearing gloves when cutting auto's. Cotton ones only NO BLACK DOTS ON GLOVES or anything that will scrape or mark up hoods ort bumpers.
- 10.Lashings must be pushed along deck out of the way. NO CARRYING THROUGH ROWS!
- 11.FOLLOW PRE DESIGNATED TRAFFIC ROUTES DON'T CUT THROUGH EMPTY LOTS.
- 12. NO FOOD OR DRINKS IN VEHICLES.